



SOUTH COAST PROPELLER SERVICE, INC.



FAA Approved Repair Station
S6PR302X

1-866-875-6377
205-426-7022
FAX 205-426-7026

5750 Durose Drive
Bessemer, AL 35022

PROPELLER LOGBOOK



OWNER NAME _____

ADDRESS _____

PROPELLER MODEL HC-C34R-1RF

BLADE MODEL F7663-R

HUB SERIAL NO. DY2087

BLADE SERIAL NO.

1 F84142


2 F84134

3 F80253

4 _____



MAINTENANCE & SERVICE HISTORY

Date	Total Propeller Time	Time Since Overhaul	Description of Work	Authorized Signatures Repairman & Station Certificate Numbers
			SOUTH COAST PROPELLER SERVICE, INC. 5750 DUROSE DRIVE, BESSEMER, AL 35022 205-426-7022 REPAIR STATION #S5PR302X	
			MAJOR OVERHAUL. BLADES REFINISHED PARTS FLORESCENT PENETRANT INSPECTED. MAGNAFLUXED, REPLATED & REPLACED WHERE REQUIRED. PROPELLER TRACKED, BALANCED SET ANGLES, GREASED & PAINTED. COMPLIES WITH AD'S & SB'S LISTED ON 8130-3 FORM. BLADE S/N# INSTALLED ARE F84142, F84134 AND F80253.	
			WORK ORDER # SR-3268 MODEL # HC-C3YR-1RF BLADE MODEL # F7663-R HUB SERIAL # DY2087 DATE 10/15/05	 JAMES M. GATHERS GENERAL MANAGER

Note: Enter Compliance with All Applicable FAA A.D. & Factory Service Bulletins on Pages 11 & 12.

MAINTENANCE & SERVICE HISTORY



Date	South Delta Aviation N8462C Tach: 3289.1	Helena-West Helena, AR 72390 SPOH: 673.6	870-572-9011 Date: 1-7-09 TTP: 2670.8	res in s
	Completed annual inspection this date. Checked spinner and bulkhead for cracks - none found. Dressed minor nicks from blades. Operational check found satisfactory. See AD list in aircraft records for details of compliance.			
	I CERTIFY THIS PROP HAS BEEN INSPECTED IN ACCORDANCE WITH A 100 HOUR INSPECTION AND FOUND TO BE IN AN AIRWORTHY CONDITION.			
	Michael D. Schlesselman A&P4839664491A			

Note: Enter Compliance with All Applicable FAA A.D. & Factory Service Bulletins on Pages 11 & 12.